

Mierniki uniwersalne / Universal meters

UT71

UT 71 A



MIE0091

UT 71 D



MIE0092

UT 71 E



MIE0093

		MIE0091	MIE0092	MIE0093
		UT71A	UT71D	UT71E
Napięcie DC	DC Voltage	0-1000V [5], (0.1%+8)	0-1000V[5], (0.025%+5)	0-1000V[5], (0.025%+5)
Napięcie AC	AC Voltage	0-1000V [4], (0.8%+40)	0-1000V[4], (0.4%+30)	0-1000V[4], (0.4%+30)
Pasmo AC	AC Bandwidth	100KHz	100KHz	100KHz
Prąd DC	DC Current	0-10A [5], (1%+20)	0-10A[5], (0.08%+8)	0-10A[5], (0.08%+8)
Prąd AC	AC Current	0-10A [5], (0.5%+50)	0-10A[5], (0.5%+15)	0-10A[5], (0.5%+15)
Rezystancja	Resistance	0-20MΩ [6], (1.5%+20)	0-40MΩ[6], (0.3%+8)	0-40MΩ[6], (0.3%+8)
Pojemność	Capacitance	0-20mF [7], (0.1%+20)	0-40mF[7], (1%+20)	0-40mF[7], (1%+20)
Temperatura	Temperature (0C)	-	-40°C ~ 1000°C, (1%+30)	-40°C ~ 1000°C, (1%+30)
Częstotliwość	Frequency	0-200MHz[8], (0.1%+15)	0-400MHz[8], (0.01%+8)	0-400MHz[8], (0.01%+8)
Współczynnik wyp.	Duty Cycle	10%~90%, (1%+30)	10%~90%, (1%+30)	10%~90%, (1%+30)
4~20mALoop	4~20mALoop	0%~100%	0~100%, (1%+50)	0~100%, (1%+50)
Pomiar mocy	Power Measurement	-	-	(2%+5)
Funkcje dodatkowe	Special functions	Bezpiecznik 10A, Autozakresy, pomiar AC + DC, Diody, Ciągłość obwodu, True RMS, Peak Hold, Max/Min, Wart względna, podtrzymanie pomiaru, USB, Podświetlenie wyświetlacza podwójne, wyświetla ikony, Sleep Mode, ostrzeżenie o słabej baterii, Max.wart wyświetlacza 20000, Analogowy Bar Graph	Bezpiecznik 10A, Autozakresy, pomiar AC + DC, Zapis pomiarów: 9999, Odczyt danych, Diody, Ciągłość obwodu, True RMS, Peak Hold, Max/Min, Wart względna, podtrzymanie pomiaru, USB, Podświetlenie wyświetlacza podwójne, wyświetla ikony, Sleep Mode, ostrzeżenie o słabej baterii, Max.wart wyświetlacza 40000, Analogowy Bar Graph	Bezpiecznik 10A, Autozakresy, pomiar AC + DC, Zapis pomiarów: 100, Odczyt danych, Diody, Ciągłość obwodu, True RMS, Peak Hold, Max/Min, Wart względna, podtrzymanie pomiaru, USB, Podświetlenie wyświetlacza podwójne, wyświetla ikony, Sleep Mode, ostrzeżenie o słabej baterii, Max.wart wyświetlacza 40000, Analogowy Bar Graph
		Fused 10A Range, Auto Ranging, Current Measurement Alarm, Function Set Up, AC + DC Measurement, Diode, Continuity Buzzer, True RMS, Peak Hold, Max/Min Mode, Relative Mode, Data Hold, USB, Double Display Backlight, Full Icon Disply, Sleep Mode, Low Battery Display, Input Impedance for DC Voltage Measurement: DC 200mV : Around 2.5GΩ, All Other Ranges : 10MΩ, Max. Display 20000, Analogue Bar Graph	Fused 10A Range, Auto Ranging, Current Measurement Alarm, Function Set Up, AC + DC Measurement, Data Logging:9999, Data Recall, Diode, Continuity Buzzer, True RMS, Peak Hold, Max/Min Mode, Relative Mode, Data Hold, USB, Double Display Backlight, Full Icon Disply, Sleep Mode, Low Battery Display, Input Impedance for DC Voltage Measurement: DC 200mV : Around 2.5GΩ, All Other Ranges : 10MΩ, Max. Display:40000, Analogue Bar Graph	Fused 10A Range, Auto Ranging, Current Measurement Alarm, Function Set Up, AC + DC Measurement, Data Logging:100, Data Recall, Diode, Continuity Buzzer, True RMS, Peak Hold, Max/Min Mode, Relative Mode, Data Hold, USB, Double Display Backlight, Full Icon Disply, Sleep Mode, Low Battery Display, Input Impedance for DC Voltage Measurement: DC 200mV : Around 2.5GΩ, All Other Ranges : 10MΩ, Max. Display:40000, Analogue Bar Graph
Zasilanie	Power	9V (6F22)	9V (6F22)	9V (6F22)
Wymiary LCD	LCD size	73 x 50 mm	73 x 50 mm	73 x 50 mm
Wymiary miernika	Product size	200 x 93 x 40mm	200 x 93 x 40mm	200 x 93 x 40mm
Masa	Weight	384g	384g	384g
Dołączone akcesoria	Standard Accessories	Przewody pomiarowe, bateria, instrukcja, krokodyle, clip, USB kabel, Software, pokrowiec	Przewody pomiarowe, bateria, instrukcja, krokodyle, clip, USB kabel, Software, pokrowiec, sonda pomiaru temp.	Przewody pomiarowe, bateria, instrukcja, krokodyle, clip, USB kabel, Software, pokrowiec, sonda pomiaru temp., zasilacz
		Test Lead, Battery, English Manual, Alligator Clip, Test Clip, USB Interface Cable, Software, Carrying Bag	Test Lead, English Manual, Battery, Alligator Clip, USB Interface Cable,Software, Point Contact Temperature, Probe, Carrying Bag, Test Clip	Test Lead, English Manual, Battery, Alligator Clip, USB Interface Cable,Software, Point Contact Temperature, Probe, Carrying Bag, Test Clip, Power Adaptor

[x] - Liczba zakresów pomiarowych / Measurement's range amount